


NL – Belangrijke waarschuwing!


Deze firmware-update is uitsluitend geschikt voor de volgende Travelvision controlboxen (type staat op de voorkant van de unit).

- E-85 Skew – MTC7812 – DVB-S2



Update E85 Skew MTC7812 DVB-S2 v10.9

- E-85 Skew – MTC7822 – DVB-S2X



Update E85 Skew MTC7822 DVB-S2X 11.2

In de download staan twee firmware-mappen, één voor elke uitvoering.

Kies altijd de juiste map die hoort bij uw controlbox en plaats de 2 bestanden **update.bin** en **mtHWInfo.txt** uit deze map op het USB station.


Gebruik geen ander bestand dan het bij uw type-nummer vermelde firmware-bestand.

Een verkeerde update kan de antenne onbruikbaar maken en valt niet onder garantie.

EN – Important Warning!


This firmware update is only suitable for the following Travelvision control boxes (the type is indicated on the front of the unit).

- **E-85 Skew – MTC7812 – DVB-S2**



Update E85 Skew MTC7812 DVB-S2 v10.9

- **E-85 Skew – MTC7822 – DVB-S2X**



Update E85 Skew MTC7822 DVB-S2X 11.2

The download contains two firmware folders, one for each version.

Always select the correct folder that matches your control box and copy the two files **update.bin** and **mtHWInfo.txt** from this folder to the USB stick.

Do not use any file other than the firmware file specified for your type number.

An incorrect update can render the antenna unusable and is not covered under warranty.